

# GENERAL MANAGER REPORT

FEBRUARY 2026

## *FIELD OPERATIONS & MAINTENANCE:*

- The monthly water sample results were absent of contamination
- Dig Alerts marking of water systems underground infrastructure
- Road grading North of Tank Site after wash-out from rain and over-flowing of the storage tanks
- Electrical conduit repaired at Well No. 2 (loss of power to the cargo container)
- Cables for the water level indicator on the 75k tank replaced
- Filters added to the venting windows on the Booster Station to prolong VFD electrical components

**Staff Comments:**

---

---

---

---

---

---

*ADMINISTRATIVE OFFICE SUMMARY*

- Customer complaints regarding the ability to read their printed postcard statement. Printing on other printer for the February statement and printer settings changed.
- SCADA system telemetry updated and is now fully operational, and on designated electrical breaker.
- Additional breaker and outlet to accommodate the increase in office equipment.

**Staff Comments:**

---

---

---

---

---

---

*MISCELLANEOUS TOPICS*

**TO DO LIST**

- Master List of the District Inventory including repair parts and supplies, hand-tools, Fuel and Electrical equipment with the locations and quantities of of each item and labeled
- Master List of the District Equipment tool Including: Dog Tags attached to all mobile equipment, Power-tools and components. The location of storage, Original purchase price and date, expected lifespan of items.
- Dog Tags to be attached to every fire hydrant to help identify during maintenance and repairs

**Staff Comments:**

---


---

---



road grading on the North side of the tank site.

Dan Smith  
February 25, 2026 14:58



Dan Smith  
February 22, 2026 16:54



Dan Smith  
February 05, 2026 09:46



Air vents/windows are now covered with a mesh filter to prolong the VDF electrical panel components

Dan Smith  
February 08, 2026 10:24



painting the booster station piping Safety Blue

Dan Smith  
February 08, 2026 10:29



well site electrical conduit rusted through shorting out the wiring, causing no lights or outlets to work inside cargo container.

Dan Smith  
February 06, 2026 09:02




Dan Smith  
February 06, 2026 09:02



Dan Smith  
February 05, 2026 08:17



Dan Smith  
February 05, 2026 11:14



Dan Smith  
February 11, 2026 18:07